Prints and/or Slides Collected for 1995-97 NEHRP Project Personalizing the Earthquake Threat Earthquake Education Services, University of Utah Seismograph Stations

Earthquake: 1962 Magna, Utah; magnitude 5.2

1 File #: P1962M02

In File: B/W8x10; digital file

Permission:

May use for educational, non-profit purposes

if credit source

Brief Description:

Biology Lab, Cyprus High School, Magna, UT

Credit:

Photo by Van Porter

Courtesy of Salt Lake Tribune, Salt Lake City, UT

Custodian Harold Thomas cleans up broken jars and specimens that fell from shelves in the biology lab of Cyprus High School.

Magna, Utah

1962 Magna, Utah earthquake; magnitude 5.2

2 File #: P1962M03

In File:

B/W9x11;digital file

Permission:

Permission given by Steven Handy July

Clean-up at Grand American Market. Salt Lake City, UT **Brief Description:**

1996 to use photos for educational slides, exhibit, and WWW. Not to be used in any

"for profit" publication.

Photo courtesy of Deseret News, Salt Lake City, UT Credit:

Manager W.H. Ross of the Grand American Market at State Street and 34th South in Salt Lake City, Utah, clears the aisle of broken preserve bottles dumped there by the earthquake.

1962 Magna, Utah earthquake; magnitude 5.2

File #: P1962M04

In File:

Permission:

Permission given by Steven Handy July

Bedroom covered with bricks and other debris. Salt Lake City, UT **Brief Description:**

B/W9x11

1996 to use photos for educational slides. exhibit, and WWW. Not to be used in any

"for profit" publication.

Photo courtesy of Deseret News, Salt Lake City, UT Credit:

Earthquake's fury was felt in this house at 17 N. Fifth West, when ceiling caved in on head of bed while Mrs. Connie Miller was resting on the foot of bed.

1962 Magna, Utah earthquake; magnitude 5.2

File #: P1962M05

In File: B/W9x11;digital file

Permission:

Permission given by Steven Handy July 1996 to use photos for educational slides,

Brief Description:

Clock stopped at 9:05 a.m. Salt Lake City, UT

exhibit, and WWW. Not to be used in any "for profit" publication.

Photo courtesy of Deseret News, Salt Lake City, UT Credit:

Electric clocks in Salt Lake City, Utah, stopped, showing the time of the quake as 9:05 a.m. 1962 Magna, Utah earthquake; magnitude 5.2

File #: P1962M06

In File: B/W9x11; digital file

Permission:

Permission given by Steven Handy July 1996 to use photos for educational slides, exhibit, and WWW. Not to be used in any "for profit" publication.

Brief Description:

Inside wall cracks, Cyprus High School. Magna, UT

Credit:

Photo courtesy of Deseret News, Salt Lake City, UT

The walls of Cyprus High School in Magna, Utah, suffered plaster cracks. According to the Desert News (9/6/1962), a "parapet around the top of the school was damaged and had to be removed."

1962 Magna, Utah earthquake; magnitude 5.2

File #: P1962M07

Brief Description:

In File: B/W9x11;digital file

Clean-up at Colosimos' Standard Market. Magna, UT

Permission:

Permission given by Steven Handy July 1996 to use photos for educational slides, exhibit, and WWW. Not to be used in any "for profit" publication.

Photo courtesy of Deseret News, Salt Lake City, UT Credit:

Ernest Colosimo, co-owner of Standard Market, Magna, Utah, cleans up bottled products which fell from shelves in the market. 1962 Magna, Utah earthquake; magnitude 5.2

Earthquake: 1962 Magna, Utah; magnitude 5.2

7 File #: P1962M08

In File: B/W3x5;digital file

Permission:

Not to be used for duplication or publication

without written permission and payment of

fees

Brief Description:

Fallen brick and resulting ceiling damage. Salt Lake City, UT

Photo by Brandt Gray, Salt Lake Tribune; file#5335

Courtesy of Utah State Historical Society; Salt Lake City, UT

Mrs. Wesemann, 430 East 7th South, Salt Lake City, Utah, was hit by falling plaster when blocks from an inner wall fell through the

1962 Magna, Utah earthquake; magnitude 5.2

File #: P1962M09

In File: B/W3x5; digital file

Permission:

Not to be used for duplication or publication without written permission and payment of

Brief Description:

South High School students and staff evacuate building. Salt

Lake City, UT

Credit:

Photo from Salt Lake Tribune collection; file#4745

Courtesy of Utah State Historical Society

Students evacuated South High School in Salt Lake City, Utah, after the earthquake, but returned to class when damage was deemed slight. The school suffered cracks around the main entrance.

1962 Magna, Utah earthquake; magnitude 5.2

File #: P1962M10

In File:

B/W3x5; digital file

Permission:

Not to be used for duplication or publication

without written permission and payment of

Brief Description:

Filing cabinets thrown open & tilted. Salt Lake City, UT

Photo from Salt Lake Tribune collection; file#5335 Credit:

Courtesy of Utah State Historical Society

Many files tipped out of cabinets in the Beneficial Life Insurance Co. offices at 47 W. South Temple. Salt Lake City, Utah 1962 Magna, Utah earthquake; magnitude 5.2

File #: P1962M11

In File:

BAV3x5; digital file

Permission:

Not to be used for duplication or publication without written permission and payment of

fees.

Brief Description:

Ceiling damage and fallen bricks in home. Salt Lake City, UT

Credit:

Photo from Salt Lake Tribune collection; file#5335

Courtesy of Utah State Historical Society

The Jacobsen home at 562 North 2nd West in Salt Lake City, Utah, was severely damaged.

1962 Magna, Utah earthquake; magnitude 5.2

File #: P1962M12

In File:

BAW3x5; digital file

Permission:

Not to be used for duplication or publication

without written permission and payment of

Brief Description:

Mother, 2 children in damaged bedroom. Salt Lake City, UT

Credit:

Photo from Salt Lake Tribune collection; file#5335

Courtesy of Utah State Historical Society

When this young mother felt the earth tremble, she grabbed her children from the bed where they were playing. Falling plaster and parts of an inner wall barely missed them. Salt Lake City, Utah

1962 Magna, Utah earthquake; magnitude 5.2

12 File #: P1962M13

In File: B/W3x5; digital file

Permission:

Not to be used for duplication or publication without written permission and payment of

Brief Description:

Woman amidst quake debris in bedroom. Salt Lake City, UT

Photo from Salt Lake Tribune collection; file#4745 Courtesy of Utah State Historical Society

According to the Salt LakeTribune (9/6/1962), Mrs. George Miller and her son were sitting on the foot of the bed in their home at 17 North 5th West in Salt Lake City, when parts of an inner wall fell on the head of the bed.

1962 Magna, Utah earthquake; magnitude 5.2

Earthquake: 1962 Magna, Utah; magnitude 5.2

13 File #: P1962M14

Brief Description:

In File: B/W3x5; digital file

Permission:

Not to be used for duplication or publication

without written permission and payment of

Connie Miller sitting on bed with quake debris; hole in ceiling; Salt

Lake City, UT

Credit:

Photo from Salt Lake Tribune collection; file#4745

Courtesy of Utah State Historical Society

According to the Salt LakeTribune (9/6/1962), Mrs. George Miller and her son were sitting on the foot of the bed in their home at 17 North 5th West in Salt Lake City, when parts of an inner wall fell on the head of the bed.

1962 Magna, Utah earthquake; magnitude 5.2

File #: P1962M15

In File: B/W9x11;digital file

Permission:

Permission given by Steven Handy July

1996 to use photos for educational slides, exhibit, and WWW. Not to be used in any

"for profit" publication.

Brief Description:

Repairing gas pipe leak. West Point, UT

Credit:

Photo courtesy of The Deseret News, Salt Lake City, UT

Gas pipe at 3000 West and 300 North in West Point, Utah, is being taped to stop a high pressure leak that occurred at the same time as the earthquake. The repair took more than 5 hours to complete. Due to the coincidence of timing, Mountain Fuel Company officials assume that the earthquake was responsible for the leak (Deseret News [9/6/1962]).

1962 Magna, Utah earthquake; magnitude 5.2