

## Earthquake: 1992 St. George, Utah; magnitude 5.8

1 **File #:** P1992001      **In File:** C8x10; digital file      **Permission:** No restrictions. Please credit sources.

**Brief Description:** Aerial view of house, road, and vehicles on landslide in Springdale, UT

**Credit:** Photo courtesy of The Salt Lake Tribune (Salt Lake City, UT) and University of Utah Seismograph Stations

Three homes were destroyed in the Balanced Rock subdivision in Springdale, Utah, when the earthquake reactivated an old landslide 30 miles away from the epicenter. The couple living in this house were unable to use their vehicles to escape the landslide.  
1992 St. George, Utah earthquake; magnitude 5.8

---

2 **File #:** P1992002      **In File:** C3x5; digital file      **Permission:** No restrictions. Please credit source.

**Brief Description:** Road to Zion National Park closed. Springdale, UT

**Credit:** Photo courtesy of Connie Snapp, Springdale, UT

A break in a water pipe occurred just outside the Springdale, Utah entrance to Zion National Park. This break, as well as the landslide, caused the park to be closed for a day.  
1992 St. George, Utah earthquake; magnitude 5.9

---

3 **File #:** P1992003      **In File:** C3x5; digital file      **Permission:** No restrictions. Please credit source.

**Brief Description:** Break in water pipe; Springdale, UT

**Credit:** Photo courtesy of Connie Snapp, Springdale, UT

The water pipe broke just outside the entrance to Zion National Park.  
1992 St. George, Utah earthquake; magnitude 5.8

---

4 **File #:** P1992004      **In File:** C3x5; digital file      **Permission:** No restrictions. Please credit source.

**Brief Description:** Entrance to Zion National Park, UT is closed.

**Credit:** Photo courtesy of Connie Snapp, Springdale, UT

Zion National Park was closed for one day after the earthquake caused the large landslide and broke the water pipe just outside its southwest entrance.  
1992 St. George, Utah earthquake; magnitude 5.8

---

5 **File #:** P1992005      **In File:** C3x5; digital file      **Permission:** No restrictions. Please credit source.

**Brief Description:** Mail truck allowed around road closure to Zion National Park. Springdale, UT

**Credit:** Photo courtesy of Connie Snapp, Springdale, UT

The road to Zion National Park was closed until safety could be determined and the road could be rebuilt around the slide. The mail truck was allowed through.  
1992 St. George, Utah earthquake; magnitude 5.8

---

6 **File #:** P1992006      **In File:** C3x5; digital file      **Permission:** No restrictions. Please credit source.

**Brief Description:** Landslide viewed from Watchman Trail, Zion National Park, UT

**Credit:** Photo courtesy of Connie Snapp, Springdale, UT

This view of the Springdale landslide is from the Watchman Trail in Zion National Park. The large landslide scarp (as high as 50 feet) is in the lower right corner of photo.  
1992 St. George, Utah earthquake; magnitude 5.8

---

## Earthquake: 1992 St. George, Utah; magnitude 5.8

7 **File #:** P1992007      **In File:** C3x5; digital file      **Permission:** No restrictions. Please credit source.

**Brief Description:** Utility poles turned to kindling by "Slide Hill"; Springdale, UT

**Credit:** Photo courtesy of Connie Snapp, Springdale, UT

Utility poles along State Route 9 were turned to kindling by the steep bulging front (toe) of the landslide as it moved laterally several meters.  
1992 St. George, Utah earthquake; magnitude 5.8

---

8 **File #:** P1992008      **In File:** C3x5; digital file      **Permission:** No restrictions. Please credit source.

**Brief Description:** Damaged house on top of Springdale, UT landslide

**Credit:** Photo courtesy of Connie Snapp, Springdale, UT

One of three houses in Balanced Rock Hills subdivision destroyed by the landsliding under it.  
1992 St. George, Utah earthquake; magnitude 5.8

---

9 **File #:** P1992009      **In File:** C3x5; digital file      **Permission:** No restrictions. Please credit source.

**Brief Description:** Rock fall in St. George, UT

**Credit:** Photo courtesy of Glen Blakley, St. George, UT

In St. George, Utah, rocks fell at the east end of Airport Hill.  
1992 St. George, Utah earthquake; magnitude 5.8

---

10 **File #:** P1992010      **In File:** C3x5; digital file      **Permission:** No restrictions. Please credit source.

**Brief Description:** Fallen plaster in St. George Art Center. St. George, UT

**Credit:** Photo courtesy of Glen Blakley, St. George, UT

Plaster damage occurred in the women's restroom in the St. George Art Center in St. George, Utah. This building is a large, two-story building constructed of unreinforced masonry.  
1992 St. George, Utah earthquake; magnitude 5.8

---

11 **File #:** P1992011      **In File:** C3x5; digital file      **Permission:** No restrictions. Please credit source.

**Brief Description:** Trophy cabinet fallen from wall in St. George Art Center. St. George, UT

**Credit:** Photo courtesy of Glen Blakley, St. George, UT

The trophy cabinet fell from the wall on the east staircase of the St. George Art Center.  
1992 St. George, Utah earthquake; magnitude 5.8

---

12 **File #:** P1992012      **In File:** C3x5; digital file      **Permission:** No restrictions. Please credit source.

**Brief Description:** Cracks in home driveway. St. George, UT

**Credit:** Photo courtesy of Glen Blakley, St. George, UT

This was one of many new cracks in the photographer's driveway at 1995 W. 1140 N. in St. George, Utah.  
1992 St. George, Utah earthquake; magnitude 5.8

---